

BULLETIN

Product Updates · News & Information

September 2011

Staining of ArmourCool white granulated cap sheets

Shortly after the manufacturing process of the IKO Armourcool Granular cap sheet, there may be the presence of a yellowish staining randomly dispersed over the surface on

individual granules. The staining is the result of light asphalt precipitants being absorbed by some of the granules, turning them from a bright white color to a tan/yellow color.

This condition is temporary. Once the Armourcool Granular cap sheet is exposed to a few weeks of weathering (both sun and rain), the color reverts back to a bright white condition exhibiting no side affects from the temporary staining.

Please note that the staining of stored roles may become more pronounced when subjected to longer and/or hotter storage periods.